

## Update on the Track Fitter(TF)



6<sup>th</sup> SVT workshop Sep. 10-11, 02 Un-ki Yang, Univ. of Chicago

- $\rightarrow$   $\phi$ =0 problem was fixed.
- A possible source of the TF failure in Flash MEM (one per 1-2 months) was eliminated.
- $\phi$ =0 problem!  $\phi = \phi_0 + \delta \phi_0 (= \mathbf{f}^* \delta \mathbf{x}, 8 \text{bits})$ (13bits from 0 to  $2\pi$ ) Negative  $\phi$  value occurs, if  $-\delta \phi_0 > \phi_0$  (around +0).

## $\phi$ =0 problem in the TF



TF vs SVTSIM in φ

- A test in B0 Teststand shows that this problem occurs at 7% rate in wedge 0.
- No problem appears with fixed version of firmware (correction was done within 8 LS bits=11°).

## ☐ Things to do!

- 1. Install updated firmware on the other 11 Rev-B TFs and 2 Rev-A TFs.
- 2. Need to fix problems in two spare TFs (Rev-B): VME block data transfer in one TF, stability check on another TF (currently, working spare boards: 1 Rev-B, 2 Rev-A TFs)